

Utility Conflict Report

OWNER	Utility	CPS		Corridor	SW MILITA	ιRY	SITE PHOTOS
 	Contact	JAKE MAR	TINEZ	ID	3131		
Ō							
GENERAL INFO	Utility		ELECTRIC				
	Size and Material		STANDARD POWER POLE, TIMBER				+
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE			JTE	
	Longitudinal or Crossing		CROSSING				
	Placement Relative to ROW		INSIDE ROW				
LOCATION	Sheet No.						L INSURANCE
	Station 5	553+37.97					ARY 922-6315
	Offset 1	15.75					
	Latitude +	-29.357618					offly AWA
	Longitude -	-98.55294					MARTINE
SUE	Level of Investigation Req'd		NONE				
	Test Hole No		N/A				
	Test Hole Depth		N/A				8
RESOLUTION	Recommended Action		NO CONFLICT				
	Estimated Resolution Date		11/21/2018				
	Resolution Status		NO RESOLUTION WAS REQUIRED				
	Comment		Back of curb to pole = 3'-0" Sidewalk width = 5'-0" No pole ID CATV cable				
	Date Collected 7/24/2018 12:21:38 PM Date Modified 11/28/2018 6:59:12 AM						

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800