

## **Utility Conflict Report**

04								
liji	Utility	SAWS		Corridor	SW MILITA	RY .	SITE PHOTOS	
OWNER	Contact	ANN PECH	E	ID	3160		H II	
GENERAL INFO	Utility		WATER				TE	
	Size and Material		STANDARD FIRE HYDRANT					
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUT			JTE		
	Longitudinal or Crossing		CROSSING					
	Placement Relative to ROW		INSIDE ROW					
LOCATION	Sheet No. 1	175						
	Station 6	607+88.74						
	Offset 2	21.5841						
	Latitude +	-29.356524						
	Longitude	-98.53595						
SUE	Level of Investigation Req'd		NONE					
	Test Hole No		N/A					
	Test Hole Depth		N/A					
RESOLUTION	Recommended Action		NO CONFLICT					
	Estimated Resolution Date							
	Resolution Status		NO RESOLUTION WAS REQUIRED					
	Comment		Hydrant to back of sidewalk = 4'-4 1/2" Sidewalk width = 5'-0"			,		
Date Collected 7/31/2018 12:41:02 PM Date Modified 11/28/2018 6:59:12 AM								