

Utility Conflict Report

OWNER	Utility	SAWS		Corridor	SW MILITAI	RY	SITE PHOTOS		
Z	Contact	ANN PECH		ID	3175	``			
O	7 ANT LOTT				3173				
INFO	Utility		SANITARY SEWER						
	Size and Material		STANDARD MANHOLE, CAST IRON						
GENERAL	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE						
GEN	Longitudinal or Crossing		CROSSING						
	Placement Relative to ROW		INSIDE ROW						
LOCATION	Sheet No. 147								
	Station 6	32+21.78							
	Offset 2	8.2892							
	Latitude +	29.356530							
	Longitude -	98.52831							
SUE	Level of Investigation Req'd		NONE						
	Test Hole No		N/A						
	Test Hole Depth		N/A						
	Recommended Action		NO CONFLICT			and the second s			
RESOLUTION	Estimated Resolution Date								
	Resolution Status		NO RESOLUTION WAS REQUIRED						
	Comment		Manhole adjacent to edge of driveway apron Unable to open manhole						
Date Collected 7/31/2018 3:46:03 PM Date Modified 11/28/2018 6:59:12 AM									

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800