

## **Utility Conflict Report**

ER	Utility	CPS		Corridor	SW MILITAI	RY	SITE PHOTOS	
OWNER	Contact	JAKE MAR	TINEZ	ID	3177			
GENERAL INFO	Utility		ELECTRIC					
	Size and Material		STANDARD POWER POLE, TIMBER					
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE			TE		
	Longitudinal or Crossing		CROSSING					
	Placement Relative to ROW		INSIDE ROW					
LOCATION	Sheet No.	148						
	Station 6	35+50.19						
	<b>Offset</b> 19.3175							
	<b>Latitude</b> +29.356500							
	Longitude	-98.52734						
SUE	Level of Investigation Req'd		NONE					
	Test Hole No		N/A					
	Test Hole Depth		N/A					
RESOLUTION	Recommended Action		NO CONFLICT					
	<b>Estimated Resolution Date</b>							
	Resolution Status		NO RESOLUTION WAS REQUIRED					
	Comment		Pole to diagonal edge of sidewalk = 4'-0" Pole to back of curb = 4'-1" Sidewalk width at pole = 7'-0" Pole to back of sidewalk = 1'-10" Pole to guy wire = 9'-4" No pole ID					
	<b>Date Collected</b> 7/31/2018 4:00:40 PM <b>Date Modified</b> 11/28/2018 6:59:12 AM							