

## **Utility Conflict Report**

ER	Utility	CPS		Corridor	SW MILITA	SITE PHOTOS		
OWNER	Contact	JAKE MAR	TINEZ	ID	3179	The state of the s		
GENERAL INFO	Utility		ELECTRIC					
	Size and Material		STANDARD POWER POLE, TIMBER					
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUT			E		
	Longitudinal or Crossing		CROSSING					
	Placement Relative to ROW		INSIDE ROW					
LOCATION	Sheet No. 148							
	Station 6	36+26.31						
	Offset 1	19.5776						
	Latitude -	+29.356615						
	Longitude	-98.52706						
SUE	Level of Investigation Req'd		NONE					
	Test Hole No		N/A					
	Test Hole Depth		N/A					
RESOLUTION	Recommended Action		NO CONFLICT					
	Estimated Resolution Date							
	Resolution Status		NO RESOLUTION WAS REQUIRED					
	Comment		Pole ID: LW 39981; 491838 Pole to back of curb = 4'-5" Sidewalk width = 6'-11"					
Date Collected         7/31/2018 4:16:23 PM         Date Modified         11/28/2018 6:59:12 AM								

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800