

Utility Conflict Report

OWNER	Utility	SAWS		Corridor	BANDERA		SITE PHOTOS		
	Contact	ANN PECH		3185					
0									
GENERAL INFO	Utility		WATER						
	Size and Material		STANDARD WATER VALVE, CAST IRON			N			
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE						
	Longitudinal or Crossing		CROSSING						
	Placement Relative to ROW		INSIDE ROW						
LOCATION	Sheet No.	279							
	Station	1484+18.08					7		
	Offset 4						FILERENDIN		
	Latitude -								
	Longitude	-98.63702							
SUE	Level of Investigation Req'd		NONE						
	Test Hole No		N/A						
	Test Hole Depth		N/A						
RESOLUTION	Recommended Action		MINIMIZE - PROTECT IN PLACE						
	Estimated Resolution Date								
	Resolution Status		UTILITY OWNER INFORMED OF UTILITY			ГΥ			
	Comment		Valve adjacent to front of sidewalk Sidewalk width = 4'-0" Top of valve to surface = 7'-9" Lid thickness = 1 5/8"						
	Date Collected 8/16/2018 10:29:43 AM Date Modified 12/19/2018 11:48:40 AM								

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800