

Utility Conflict Report

OWNER	Utility	tility CPS		Corridor	BANDERA		SITE PHOTOS
N N	Contact	JAKE MAR	ΓINEZ	ID	3188		
0							
GENERAL INFO	Utility		ELECTRIC				
	Size and Material		STANDARD POWER POLE, TIMBER				
	Accessible Route		ASSET IS OUTSIDE ACCESSIBLE ROUTE		UTE		
	Longitudinal or Crossing		CROSSING				
	Placement Relative to ROW		INSIDE ROW				
LOCATION	Sheet No.						44
	Station						
	Offset						
	Latitude +29.521516						
	Longitude -	-98.63861					
SUE	Level of Investiga	ntion Req'd	NONE				
	Test Hole No		N/A				
	Test Hole Depth		N/A				
RESOLUTION	Recommended A	ction	NO CONFLIC	т			
	Estimated Resolution Date		8/28/2018				
	Resolution Status		NO RESOLUTION WAS REQUIRED				
	Comment		Pole diameter Pole to sidewa		10"		R 52610
	Date Collected 8/16/2018 11:02:22 AM Date Modified 11/28/2018 6:59:12 AM						