

Utility Conflict Report

OWNER	Utility	CPS		Corridor	BANDERA 3193	SITE PHOTOS
	Contact	JAKE MAR	ΓINEZ			The state of the s
O						
GENERAL INFO	Utility		ELECTRIC			
	Size and Material		STANDARD POWER POLE, TIMBER			
	Accessible Route		ASSET IS OUTSIDE ACCESSIBLE ROUTE		E	
	Longitudinal or Crossing		CROSSING		A STATE OF THE RESERVE ASSESSMENT	
	Placement Relative to ROW		INSIDE ROW			
LOCATION	Sheet No.					
	Station					
	Offset					
	Latitude +29.515487					
	Longitude -98.63429					
SUE	Level of Investigation Req'd		NONE			
	Test Hole No		N/A			
	Test Hole Depth		N/A			
RESOLUTION	Recommended Action		NO CONFLICT			
	Estimated Resolution Date		9/12/2018			
	Resolution Status		NO RESOLUTION WAS REQUIRED			
	Comment		Pole diameter Back of concr No pole ID	oncrete to pole = 4"		
	Date Collected 8/16/2018 1:17:50 PM Date Modified 11/28/2018 6:59:12 AM					