

## **Utility Conflict Report**

<b>LER</b>	Utility	CPS		Corridor	BANDERA	SITE PHOTOS
OWNER	Contact	JAKE MAR	TINEZ	ID	3196	
GENERAL INFO	Utility		ELECTRIC			
	Size and Material		STANDARD POWER POLE, TIMBER			
	Accessible Route		ASSET IS OUTSIDE ACCESSIBLE ROUTE			
	Longitudinal or Crossing		CROSSING			
	Placement Relative to ROW		INSIDE ROW			
LOCATION	Sheet No.					
	Station					
	Offset					
	<b>Latitude</b> +29.519291					
	Longitude -98.63691					E .
SUE	Level of Investigation Req'd		NONE			
	Test Hole No		N/A N/A			
	Test Hole Depth					
RESOLUTION	Recommended Action		NO CONFLICT			
	Estimated Resolution Date		8/28/2018			A CANA
	Resolution Status		NO RESOLUTION WAS REQUIRED			
	Comment		Pole diameter No pole ID Back of curb to Edge of sidew	o pole = 7'-4		

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800

11/28/2018 6:59:12 AM

**Date Modified** 

**Date Collected** 

8/16/2018 2:03:33 PM