

Utility Conflict Report

OWNER	Utility	CPS		Corridor	BANDERA	,	SITE PHOTOS	
	Contact	JAKE MAR	INEZ	ID	3216			
GENERAL INFO	Utility		ELECTRIC					
	Size and Material		STANDARD POWER POLE, TIMBER					
	Accessible Route		ASSET IS OUTSIDE ACCESSIBLE ROUTE			OUTE		
	Longitudinal or Crossing		CROSSING					
	Placement Relative to ROW		INSIDE ROW					
LOCATION	Sheet No.							
	Station							
	Offset							
	Latitude +	titude +29.500567						
	Longitude -98.62458							
SUE	Level of Investigation Req'd		NONE					
	Test Hole No		N/A					
	Test Hole Depth		N/A					
RESOLUTION	Recommended Action		NO CONFLICT					
	Estimated Resolution Date		8/28/2018					
	Resolution Status		NO RESOLUTION WAS REQUIRED					
	Comment		Pole diameter = 10" Face of wall to pole = 2'-7" No pole ID					
	Date Collected 8/17/2018 1:31:11 PM Date Modified 11/28/2018 6:59:12 AM							

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800