

Utility Conflict Report

- 4	I					
VER.	Utility	CPS		Corridor	BANDERA	SITE PHOTOS
OWNER	Contact	JAKE MAR	TINEZ	ID	3225	ictro-C
GENERAL INFO	Utility		ELECTRIC			Sent states such
	Size and Material		STANDARD POWER POLE, TIMBER			
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE			
	Longitudinal or Crossing		CROSSING			
	Placement Relative to ROW		INSIDE ROW			
LOCATION	Sheet No.					
	Station					
	Offset					
	Latitude +29.496122					
	Longitude -98.62017					
SUE	Level of Investigation Req'd		NONE			
	Test Hole No		N/A N/A			
	Test Hole Depth					
RESOLUTION	Recommended Action		NO CONFLICT			
	Estimated Resolution Date		8/28/2018 NO RESOLUTION WAS REQUIRED			
	Resolution Status					
	Comment		No pole ID Pole adjacent Typical sidewa Pole diameter	alk width = 4		

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800

11/28/2018 6:59:12 AM

Date Modified

Date Collected

8/20/2018 8:26:48 AM