

## Utility Conflict Report

<b>OWNER</b>	Utility	CPS	Corridor	BANDERA	<b>SITE PHOTOS</b>
	Contact	JAKE MARTINEZ	ID	3246	
<b>GENERAL INFO</b>	Utility	ELECTRIC			
	Size and Material	STANDARD POWER POLE, TIMBER			
	Accessible Route	ASSET IS INSIDE ACCESSIBLE ROUTE			
	Longitudinal or Crossing	CROSSING			
	Placement Relative to ROW	INSIDE ROW			
<b>LOCATION</b>	Sheet No.				
	Station				
	Offset				
	Latitude	+29.490543			
	Longitude	-98.61253			
<b>SUE</b>	Level of Investigation Req'd	NONE			
	Test Hole No	N/A			
	Test Hole Depth	N/A			
<b>RESOLUTION</b>	Recommended Action	NO CONFLICT			
	Estimated Resolution Date	8/28/2018			
	Resolution Status	NO RESOLUTION WAS REQUIRED			
	Comment	Front of sidewalk to pole = 2'-10" Pole diameter = 10" No pole ID			
<b>Date Collected</b>		8/20/2018 10:32:35 AM	<b>Date Modified</b>		11/28/2018 6:59:12 AM

