

Utility Conflict Report

α						SITE PHOTOS
빌	Utility CPS		Corridor	BANDERA	3112 PHOTO3	
OWNER	Contact	JAKE MAR	TINEZ	ID	3248	
INFO	Utility		ELECTRIC			
	Size and Material		STANDARD POWER POLE, TIMBER			
GENERAL	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE			
GEN	Longitudinal or Crossing		CROSSING			
	Placement Relative to ROW		INSIDE ROW			
LOCATION	Sheet No.					
	Station					
	Offset					10418
	Latitude +29.490910					
	Longitude -98.61305					Minis
SUE	Level of Investigation Req'd		NONE			
	Test Hole No		N/A			THE CALL STATE OF THE CALL STA
	Test Hole Depth		N/A			
RESOLUTION	Recommended Action		NO CONFLICT			
	Estimated Resolution Date		8/28/2018			
	Resolution Status		NO RESOLUTION WAS REQUIRED			
	Comment		Pole diameter Back of sidewa		= 3'-4"	

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800

11/28/2018 6:59:12 AM

Date Modified

Date Collected

8/20/2018 10:38:50 AM