

## **Utility Conflict Report**

ER.	Utility	CPS		Corridor	NOGALITO	ns	SITE PHOTOS	
OWNER			TINEZ	ID	4063	,5		
	Contact	JAKE MAR						
GENERAL INFO	Utility		ELECTRIC				FOOD TO GO	
	Size and Material		STANDARD POWER POLE, TIMBER					
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE			JTE		
	Longitudinal or Crossing		CROSSING					
	Placement Relative to ROW		INSIDE ROW					
LOCATION	Sheet No.							
	Station 1	120+39.81					Transaction .	
	Offset -	23.8256						
	Latitude -	+29.390596						
	Longitude	-98.52034						
SUE	Level of Investigation Req'd		NONE					
	Test Hole No		N/A					
	Test Hole Depth		N/A					
RESOLUTION	Recommended Action		NO CONFLICT					
	<b>Estimated Resolution Date</b>		8/13/2018					
	Resolution Status		NO RESOLUTION WAS REQUIRED					
	Comment		Pole ID: LW 43459; PL 491148					
			Pole marking: 2409 Pole to back of sidewalk = 4'-1"					
8								
							The state of the s	
	Date Collected         7/10/2018 9:30:19 AM         Date Modified         8/14/2018 4:38:26 PM							

TBPE Firm Registration #470 | TBPLS Firm Registration #10028800