

Utility Conflict Report

ER	Utility	CPS		Corridor	NOGALITOS	SITE PHOTOS
OWNER	Contact	JAKE MAR	TINEZ	ID	4072	
GENERAL INFO	Utility		ELECTRIC			
	Size and Material		STANDARD POWER POLE, TIMBER			
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE			
	Longitudinal or Crossing		CROSSING			
	Placement Relative to ROW		INSIDE ROW			
LOCATION	Sheet No.	o . 80				
	Station	125+12.89				
	Offset 22.68 Latitude +29.391724					
	Longitude	-98.51927				
SUE	Level of Investigation Req'd		NONE			
	Test Hole No		N/A			
	Test Hole Depth		N/A			
RESOLUTION	Recommended Action		MINIMIZE - PROTECT IN PLACE			
	Estimated Resolution Date					
	Resolution Status		UTILITY OWNER INFORMED OF UTILITY			
	Comment		Pole marking: P3445 Pole to face of wall = 2'-6" Sidewalk width (at pole) = 4'-9" Sidewalk width (typical) = 4'-0"			
	Date Collected	7/10/2018 1:	:38:25 PM	Date I	Modified 9/13	3/2018 2:01:29 PM
	Date Collected 7/10/2018 1:38:25 PM Date Modified 9/13/2018 2:01:29 PM					

TBPE Firm Registration #470 | TBPLS Firm Registration #10028800