

Utility Conflict Report

OWNER	Utility	CPS		Corridor	NOGALITO	os	SITE PHOTOS	
	Contact	JAKE MAR	TINEZ	ID	4079		1.3	
0								
GENERAL INFO	Utility		ELECTRIC					
	Size and Material		STANDARD POWER POLE, TIMBER					
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE					
	Longitudinal or Crossing		CROSSING					
	Placement Relative to ROW		INSIDE ROW					
LOCATION	Sheet No.							
	Station 1	32+27.97						
	Offset -	28.506						
	Latitude +	-29.393209						
	Longitude	-98.51808						
SUE	Level of Investigation Req'd		NONE					
	Test Hole No		N/A					
	Test Hole Depth		N/A					
RESOLUTION	Recommended Action		NO CONFLICT					
	Estimated Resolution Date		8/13/2018					
	Resolution Status		NO RESOLUTION WAS REQUIRED					
	Comment		Pole marking: Pole to back o Pole diameter	of curb = 5'-3"				
	Date Collected 7/10/2018 3:17:44 PM Date Modified 8/14/2018 4:38:26 PM							

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800