

Utility Conflict Report

OWNER	Utility	CPS		Corridor ID	SW MILITAI	RY	SITE PHOTOS	
	Contact	JAKE MAR	ΓINEZ		4086			
GENERAL INFO	Utility		ELECTRIC					
	Size and Material		STANDARD POWER POLE, TIMBER					
	Accessible Route		ASSET IS OUTSIDE ACCESSIBLE ROUTE		OUTE			
	Longitudinal or Crossing		CROSSING					
	Placement Relative to ROW		INSIDE ROW					
LOCATION	Sheet No.	129						
	Station	531+26.40						
	Offset 2	27.8306						
	Latitude -	+29.358160						
	Longitude	-98.56000						
SUE	Level of Investigation Req'd		NONE					
	Test Hole No		N/A					
	Test Hole Depth		N/A					
RESOLUTION	Recommended Action		NO CONFLICT					
	Estimated Resolution Date		8/14/2018					
	Resolution Status		NO RESOLUTION WAS REQUIRED					
	Comment		Pole ID: LW 38342; 452735 Pole to back of sidewalk = 9'-5" Adjacent to existing VIA bus stop					
Date Collected 7/23/2018 8:09:12 AM Date Modified 11/28/2018 6:59:12 AM								

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800