

Utility Conflict Report

ER	Utility	SAWS		Corridor	SW MILITA	RY	SITE PHOTOS		
OWNER	Contact	ANN PECH		4093					
0									
GENERAL INFO	Utility		WATER						
	Size and Material		STANDARD WATER VALVE, CAST IRON			RON			
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE			TE			
	Longitudinal or Crossing		CROSSING						
	Placement Relative to ROW		INSIDE ROW						
LOCATION	Sheet No.								
	Station 5	33+84.16							
	Offset 1	3.22							
	Latitude +	-29.358241							
	Longitude -	-98.55904							
SUE	Level of Investigation Req'd		NONE						
	Test Hole No		N/A						
	Test Hole Depth		N/A						
RESOLUTION	Recommended Action		NO CONFLICT						
	Estimated Resolution Date		11/21/2018						
	Resolution Status		NO RESOLUTION WAS REQUIRED						
	Comment		Top of valve to surface = 4'-7" Lid thickness = 2" Sidewalk width = 6'-0" Back of sidewalk to valve = 4'-9"						
Date Collected 7/23/2018 9:19:26 AM Date Modified 11/28/2018 6:59:12 AM									

TBPE Firm Registration #470 | TBPLS Firm Registration #10028800