

Utility Conflict Report

ER	Utility	SAWS		Corridor	SW MILITAF	₹Y	SITE PHOTOS		
OWNER	Contact	ANN PECH	E	ID	4106				
GENERAL INFO	Utility		WATER						
	Size and Material		STANDARD WATER VALVE, CAST IRON						
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE						
	Longitudinal or Crossing		CROSSING						
	Placement Relative to ROW		INSIDE ROW				0 2 69		
LOCATION	Sheet No.	130							
	Station 5	539+65.54							
	Offset 13.98								
	Latitude +29.357976								
	Longitude -98.55724								
SUE	Level of Investigation Req'd		NONE						
	Test Hole No		N/A						
	Test Hole Depth		N/A						
RESOLUTION	Recommended Action		MINIMIZE - PROTECT IN PLACE						
	Estimated Resolution Date								
	Resolution Status		UTILITY OWNER INFORMED OF UTILITY			LITY			
	Comment		Bottom of valve to surface = 4'-5" Lid thickness = 2" Back of sidewalk to valve = 4'-4" Sidewalk width = 6' Back of curb to valve = 1'-1"						
	Date Collected 7/23/2018 12:15:56 PM Date Modified 11/28/2018 6:59:12 AM								

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800