

Utility Conflict Report

LER	Utility	CPS		Corridor	SW MILITA	ARY	SITE PHOTOS		
OWNER	Contact	JAKE MAR	TINEZ	ID	4117		4.		
GENERAL INFO	Utility		ELECTRIC						
	Size and Material		STANDARD POWER POLE, TIMBER						
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE						
	Longitudinal or Crossing		CROSSING						
	Placement Relative to ROW		INSIDE ROW						
LOCATION	Sheet No. 1	38							
	Station 5	660+08.88							
	Offset 1	5.35							
	Latitude +	-29.357457							
	Longitude	-98.55101							
SUE	Level of Investigation Req'd		NONE						
	Test Hole No		N/A N/A						
0,	Test Hole Depth								
RESOLUTION	Recommended Action		NO CONFLIC	Т					
	Estimated Resolution Date								
	Resolution Status		NO RESOLUTION WAS REQUIRED						
	Comment		Pole ID: LA17 Pole to back o Sidewalk width CATV cable Relocate pole cantilevered to	of curb = 2'-6 n = 2'-11" to ROW wit	6 1/2" th electric lin		THE RELEASE OF THE PARTY OF THE		
	Date Collected 7/27/2018 9:05:17 AM Date Modified 12/18/2018 4:00:06 PM								

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800