

## **Utility Conflict Report**

OWNER	Utility	ility SAWS		Corridor	SW MILITA	RY	SITE PHOTOS
	Contact ANN PECHE		E <b>ID</b>		4123		18171
GENERAL INFO	Utility		SANITARY SEWER				
	Size and Material		STANDARD MANHOLE, CAST IRON				
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROU		TE /		
	Longitudinal or Crossing		CROSSING				
	Placement Relative to ROW		INSIDE ROW				
LOCATION	Sheet No.	138					The state of the s
	Station 5	563+77.23					
	Offset	17.17					
	Latitude -	+29.357293				7	44
	Longitude	-98.54975					Fa
SUE	Level of Investigation Req'd		NONE				
	Test Hole No		N/A				
	Test Hole Depth		N/A			1	
RESOLUTION	Recommended Action		NO CONFLICT				
	Estimated Resolution Date		12/17/2018				
	Resolution Status		NO RESOLUTION WAS REQUIRED				
	Comment		Manhole to back of curb = 3'-11"  Bottom of cone to surface = 1'-7"  Lid thickness = 1 1/2"  Sidewalk width = 6'-0"				
	Date Collected         7/27/2018 10:04:43 AM         Date Modified         12/17/2018 10:04:43 AM						3 10:28:01 AM