

Utility Conflict Report

						_	
IER	Utility	CPS		Corridor	SW MILITAR	SITE F	PHOTOS
OWNER	Contact	JAKE MAR	TINEZ	ID	4168		
GENERAL INFO	Utility		ELECTRIC				*
	Size and Material		STANDARD POWER POLE, TIMBER				
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUT		E		
	Longitudinal or Crossing		CROSSING				A
	Placement Relative to ROW		INSIDE ROW			1/4	
LOCATION	Sheet No. 1	58					
	Station 6	86+62.46				1	
	Offset 1	7.1907					
	Latitude +29.356527						
	Longitude .	-98.51136					
SUE	Level of Investigation Req'd		NONE				
	Test Hole No		N/A				
	Test Hole Depth		N/A				
RESOLUTION	Recommended Action		NO CONFLICT				
	Estimated Resolution Date						1
	Resolution Status		NO RESOLUTION WAS REQUIRED				
	Comment		Pole ID: LW 37937; 484266 Back of curb to pole = 3'-3" Back of sidewalk to pole = 4'-3/2" Sidewalk width = 4'-0"		3"		
Date Collected 8/2/2018 10:42:52 AM Date Modified 11/28/2018 6:59:12 AM							λM

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800