

Utility Conflict Report

ER	Utility	SAWS		Corridor	SW MILITA	RY	SITE PHOTOS		
OWNER	Contact	ANN PECH		4175					
0									
GENERAL INFO	Utility		SANITARY SEWER						
	Size and Material		STANDARD MANHOLE, CAST IRON						
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE				ITE		
	Longitudinal or Crossing		CROSSING						
	Placement Relative to ROW		INSIDE ROW						
LOCATION	Sheet No.					ROPRACTIC			
	Station 6	94+38.66							
	Offset 1	8.8178							
	Latitude +	29.356561							
	Longitude -	98.50876							
SUE	Level of Investigation Req'd		NONE						
	Test Hole No		N/A						
	Test Hole Depth		N/A						
RESOLUTION	Recommended Action		NO CONFLICT						
	Estimated Resolution Date								
	Resolution Status		NO RESOLUTION WAS REQUIRED						
	Comment		Back of curb to manhole = 4'-8.5" Sidewalk width = 6'-0" Unable to open manhole						
Date Collected 8/2/2018 12:41:16 PM Date Modified 11/28/2018 6:59:12 AM									

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800