

## **Utility Conflict Report**

OWNER	Utility	CPS		Corridor	SW MILITA	RY	SITE PHOTOS
	Contact	JAKE MAR	TINEZ	ID	4179		
0							
GENERAL INFO	Utility		ELECTRIC				
	Size and Material		STANDARD POWER POLE, TIMBER				-
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROU			JTE	E
	Longitudinal or Crossing		CROSSING				
	Placement Relative to ROW		INSIDE ROW				1 de la constante de la consta
LOCATION	Sheet No.	160					
	Station 6	696+13.29					
	Offset	16.74					
	Latitude -	+29.356542					PREMIER Uppliances determines
	Longitude	-98.50829					omputers
SUE	Level of Investigation Req'd		NONE				
	Test Hole No		N/A				
	Test Hole Depth		N/A				
RESOLUTION	Recommended Action		NO CONFLICT				
	Estimated Resolution Date						
	Resolution Status		NO RESOLUTION WAS REQUIRED				
	Comment		Pole ID: 38990 Back of sidew Back of curb to Sidewalk widtl	alk to pole = o pole = 3'-			
Date Collected 8/2/2018 1:02:35 PM Date Modified 12/18/2018 4:00:50 PM							018 4:00:50 PM