

Utility Conflict Report

| 2 | | | | | | SITE PHOTOS | | |
|--------------|------------------------------|--------------------|---|-------------------------------|-------------|-------------|--|--|
| NE | Utility | CPS | | Corridor | SW MILITARY | 01121110100 | | |
| OWNER | Contact | JAKE MAR | TINEZ | ID | 4184 | | | |
| GENERAL INFO | Utility | | ELECTRIC | | | | | |
| | Size and Material | | STANDARD POWER POLE, TIMBER | | | | | |
| | Accessible Route | | ASSET IS INSIDE ACCESSIBLE ROUTE | | | | | |
| | Longitudinal or Crossing | | CROSSING | | | | | |
| | Placement Relative to ROW | | INSIDE ROW | | | | | |
| LOCATION | Sheet No. 1 | 61 | | | | man. | | |
| | Station 7 | 01+16.11 | | | | | | |
| | Offset 1 | ffset 15.95 | | | | | | |
| | Latitude +29.356686 | | | | | motro? 3 | | |
| | Longitude -98.50682 | | | | | + | | |
| SUE | Level of Investigation Req'd | | NONE | | | | | |
| | Test Hole No | | N/A | | | | | |
| | Test Hole Depth | | N/A | | | | | |
| RESOLUTION | Recommended Action | | NO CONFLICT | | | | | |
| | Estimated Resolution Date | | 11/21/2018 | | | | | |
| | Resolution Status | | NO RESOLUTION WAS REQUIRED | | | | | |
| | Comment | | Pole ID: 40209 Pole to back o Pole to back o Sidewalk width | f curb = 2'-8 f sidewalk = | 3" | | | |

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800

11/28/2018 6:59:12 AM

Date Modified

8/6/2018 9:01:57 AM

Date Collected