

Utility Conflict Report

| | | | | | |
|---------------------|-------------------------------------|--|----------------------|-----------------------|--------------------|
| OWNER | Utility | CPS | Corridor | SW MILITARY | SITE PHOTOS |
| | Contact | JAKE MARTINEZ | ID | 4204 | |
| GENERAL INFO | Utility | ELECTRIC | | | |
| | Size and Material | STANDARD POWER POLE, TIMBER | | | |
| | Accessible Route | ASSET IS INSIDE ACCESSIBLE ROUTE | | | |
| | Longitudinal or Crossing | CROSSING | | | |
| | Placement Relative to ROW | INSIDE ROW | | | |
| LOCATION | Sheet No. | 162 | | | |
| | Station | 717+51.49 | | | |
| | Offset | 15.08 | | | |
| | Latitude | +29.356577 | | | |
| | Longitude | -98.50159 | | | |
| SUE | Level of Investigation Req'd | NONE | | | |
| | Test Hole No | N/A | | | |
| | Test Hole Depth | N/A | | | |
| RESOLUTION | Recommended Action | NO CONFLICT | | | |
| | Estimated Resolution Date | | | | |
| | Resolution Status | NO RESOLUTION WAS REQUIRED | | | |
| | Comment | Pole to back of curb = 2'-10" Pole to back of sidewalk = 2'- 10 1/2" Sidewalk width = 6'-9" No pole ID TxDOT Traffic Signal Pole to be relocated | | | |
| | Date Collected | 8/6/2018 1:03:44 PM | Date Modified | 12/18/2018 4:02:35 PM | |

