

## **Utility Conflict Report**

OWNER	Utility	CPS	TINEZ	Corridor ID	SW MILITAI 4216	RY	SITE PHOTOS
	Contact	JAKE MAR					
GENERAL INFO	Utility		ELECTRIC				
	Size and Material		STANDARD POWER POLE, TIMBER				
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROU		TE		
	Longitudinal or Crossing		CROSSING				munan
	Placement Relative to ROW		INSIDE ROW				
LOCATION	Sheet No.	166					
	Station 7	722+00.35					
	Offset	16.06					
	Latitude -	+29.356581				7	
	Longitude	-98.50021				*	
SUE	Level of Investigation Req'd		NONE			4	
	Test Hole No		N/A				, III .
	Test Hole Depth		N/A				
RESOLUTION	Recommended Action		NO CONFLICT				
	Estimated Resolution Date						
	Resolution Status		NO RESOLUTION WAS REQUIRED				
	Comment		Pole ID: 3869 Back of curb to Sidewalk widtl Back of sidew	o pole = 3'-6 h = 6'-4"			
Date Collected 8/7/2018 9:00:09 AM Date Modified 12/18/2018 4:02:39 PM							

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800