

Utility Conflict Report

ER	Utility	AT&T		Corridor	SW LOOP 4	110	SITE PHOTOS		
OWNER	Contact	PHILIP AUS	STIN	ID	7007				
0									
GENERAL INFO	Utility		COMMUNICATIONS						
	Size and Material		STANDARD MANHOLE, CAST IRON						
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE						
	Longitudinal or Crossing		CROSSING						
	Placement Relative to ROW		INSIDE ROW						
LOCATION	Sheet No.								
	Station 2	280+48.76							
	Offset -	17.1895							
	Latitude +	29.373391							
	Longitude -	-98.63829							
SUE	Level of Investigation Req'd		NONE						
	Test Hole No		N/A						
	Test Hole Depth		N/A						
RESOLUTION	Recommended Action		NO CONFLICT						
	Estimated Resolution Date		8/13/2018						
	Resolution Status		NO RESOLUTION WAS REQUIRED						
	Comment		Unable to open manhole Edge of pavement to manhole = 2'-7" Manhole to face of retaining wall = 4'-4"						
	Date Collected 8/2/2018 9:12:58 AM Date Modified 8/14/2018 4:38:26 PM								

TBPE Firm Registration #470 | TBPLS Firm Registration #10028800