

Utility Conflict Report

ER	Utility	SAWS		Corridor	MILITARY		SITE PHOTOS
OWNER	Contact	ANN PECH	E	ID	7011		
GENERAL INFO	Utility		SANITARY SEWER				
	Size and Material		STANDARD MANHOLE, CAST IRON				
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE				
	Longitudinal or Crossing		CROSSING				
ြ	Placement Relative to ROW		INSIDE ROW				
_	Sheet No.	227					
LOCATION	Station	1091+74.72					
	Offset	37.4182					
	Latitude -	atitude +29.353515					
	Longitude	-98.42488					
SUE	Level of Investigation Req'd		NONE				
	Test Hole No		N/A				
0,	Test Hole Depth		N/A				
	Recommended Action		NO CONFLICT				
	Estimated Resolution Date		8/13/2018				
Z	Resolution Status		NO RESOLUTION WAS REQUIRED				
RESOLUTIO	Comment		Manhole in middle of roadway Unable to open manhole				
Date Collected 8/2/2018 10:58:23 AM Date Modified 11/28/2018 6:59:12 AM							

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800