

Utility Conflict Report

OWNER	Utility	SAWS		Corridor	MILITARY		SITE PHOTOS		
N N	Contact ANN PECHI		E	ID	7016				
0			_						
GENERAL INFO	Utility		WATER						
	Size and Material		STANDARD WATER VALVE, CAST IRON						
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE			TE			
	Longitudinal or Crossing		CROSSING						
	Placement Relative to ROW		INSIDE ROW						
LOCATION	Sheet No. 217								
	Station 1	099+53.06							
	Offset 28.17								
	Latitude +29.354199								
	Longitude -98.42257								
SUE	Level of Investigation Req'd		NONE						
	Test Hole No		N/A						
	Test Hole Depth		N/A						
RESOLUTION	Recommended Action		NO CONFLICT						
	Estimated Resolution Date		12/18/2018						
	Resolution Status		NO RESOLUTION WAS REQUIRED						
	Comment		Water valve in right turn lane Unable to open lid Face of curb to valve = 5" Raise valve cover flush with pavement improvements			:			
	Date Collected 8/2/2018 1:52:26 PM Date Modified 12/18/2018 3:34 PM								