

Utility Conflict Report

IER.	Utility	SAWS		Corridor	SW MILITARY	SITE PHOTOS
OWNER	Contact ANN PECH		HE ID	7028		
	Utility		SANITARY SEWER			
INFO	Size and Material		STANDARD MANHOLE, CAST IRON			
GENERAL II	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE			
IÑ.	Longitudinal or Crossing		CROSSING			1 / / /
0	Placement Relative to ROW		INSIDE ROW			
LOCATION	Sheet No. 2	212				
	Station	951+77.75				
	Offset -	19.15				
lo.	Latitude -	+29.356867				
	Longitude	-98.50021				
SUE	Level of Investigation Req'd		NONE			
	Test Hole No		N/A			
0,	Test Hole Depth		N/A			
	Recommended Action		MINIMIZE - PROTECT IN PLACE			
	Estimated Resolution Date					
Z	Resolution Status		UTILITY OWNER INFORMED OF UTILITY			
TION	Comment		Bottom of cone to bottom of lid = 2'-3"			
RESOLU						

8/3/2018 8:12:14 AM

Date Collected

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800

11/28/2018 6:59:12 AM

Date Modified