

## **Utility Conflict Report**

IER	Utility	CPS		Corridor	SW MILITARY	SITE PHOTOS
OWNER	Contact	JAKE MAR	TINEZ	ID	7035	
GENERAL INFO	Utility		ELECTRIC			
	Size and Material		STANDARD POWER POLE, TIMBER			
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE			
	Longitudinal or Crossing		CROSSING			
	Placement Relative to ROW		INSIDE ROW			
LOCATION	Sheet No. 211					
	Station 9	947+59.03				
	Offset -17.84 Latitude +29.356827					
						775937
	<b>Longitude</b> -98.50148					
SUE	Level of Investigation Req'd		NONE			
	Test Hole No		N/A N/A			
	Test Hole Depth					
RESOLUTION	Recommended Action		NO CONFLICT			
	Estimated Resolution Date					
	Resolution Status		NO RESOLUTION WAS REQUIRED			
	Comment		Pole diameter Back of curb to Pole includes	o pole = 2'-		

12/18/2018 4:01:16 PM

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800

**Date Modified** 

8/3/2018 8:37:50 AM

**Date Collected**