

Utility Conflict Report

OWNER	Utility	SAWS		Corridor	SW MILITARY	ιRY	SITE PHOTOS		
N N	Contact ANN PECHI				7040				
Ó									
GENERAL INFO	Utility		SANITARY SEWER						
	Size and Material		STANDARD MANHOLE, CAST IRON						
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE			JTE			
	Longitudinal or Crossing		CROSSING						
	Placement Relative to ROW		INSIDE ROW						
LOCATION	Sheet No.	211					1		
	Station	944+77.30							
	Offset -	-19.1079							
	Latitude -	+29.356867							
	Longitude	-98.50236							
SUE	Level of Investigation Req'd		NONE						
	Test Hole No		N/A						
	Test Hole Depth		N/A						
RESOLUTION	Recommended Action		MINIMIZE - PROTECT IN PLACE						
	Estimated Resolution Date								
	Resolution Status		UTILITY OWNER INFORMED OF UTILITY			ILITY			
	Comment		Manhole ID: 1131757 Unable to open manhole Back of curb to manhole = 4'-0"						
Date Collected 8/3/2018 9:07:21 AM Date Modified 12/18/2018 8:11:20 AM									

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800