

## **Utility Conflict Report**

OWNER	Utility	SAWS		Corridor	SW MILITARY	SITE PHOTOS		
	Contact	-		ID	7043	<b>(</b> )////////////////////////////////////		
0								
GENERAL INFO	Utility		SANITARY SEWER					
	Size and Material		STANDARD MANHOLE, CAST IRON					
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE					
	Longitudinal or Crossing		CROSSING					
	Placement Relative to ROW		INSIDE ROW					
LOCATION	Sheet No.	209						
	Station	930+27.14						
	Offset	<b>set</b> -18.09						
	Latitude	+29.356706						
	Longitude	-98.50701						
SUE	Level of Investigation Req'd		NONE					
	Test Hole No		N/A					
	Test Hole Depth		N/A					
RESOLUTION	Recommended Action		MINIMIZE - PROTECT IN PLACE			Tid I		
	Estimated Resolution Date							
	Resolution Status		UTILITY OWNER INFORMED OF UTILITY					
	Comment		Unable to open manhole					
			Back of curb to manhole = 3'-4"					
	Date Collected 8/3/2018 9:30:33 AM Date Modified 11/28/2018 6:59:12 AM							

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800