

Utility Conflict Report

ER	Utility	SAWS		Corridor	SW MILITAI	RY	SITE PHOTOS		
OWNER	Contact	ANN PECH		7045					
Ō									
GENERAL INFO	Utility		SANITARY SEWER						
	Size and Material		SANITARY SEWER CLEANOUT						
	Accessible Route		ASSET IS OUTSIDE ACCESSIBLE ROUTE		OUTE				
	Longitudinal or Crossing		CROSSING						
	Placement Relative to ROW		INSIDE ROW						
LOCATION	Sheet No. 2	:09							
	Station 9	29+43.30					0.0		
	Offset -2	22.8629							
	Latitude +	29.356897							
	Longitude -	-98.50726							
SUE	Level of Investigation Req'd		NONE						
	Test Hole No		N/A						
	Test Hole Depth		N/A						
RESOLUTION	Recommended Action		NO CONFLICT				The second secon		
	Estimated Resolution Date								
	Resolution Status		NO RESOLUTION WAS REQUIRED						
	Comment		Top of cleanout to surface = 2.4" Lid thickness = 1 5/8" Cleanout to edge of concrete driveway apron = 2'-9"						
Date Collected 8/3/2018 9:39:03 AM Date Modified 11/28/2018 6:59:12 AM									

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800