

## **Utility Conflict Report**

<b>LER</b>	Utility	CPS		Corridor	SW MILITA	RY .	SITE PHOTOS	
OWNER	Contact	JAKE MAR	TINEZ	ID	7048			
GENERAL INFO	Utility		ELECTRIC					
	Size and Material		STANDARD POWER POLE, TIMBER					
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE			JTE		
	Longitudinal or Crossing		CROSSING					
	Placement Relative to ROW		INSIDE ROW					
LOCATION	Sheet No. 2	208						
	Station 9	927+39.85						
	Offset -	22.37						
	Latitude -	29.356823					XOCH DI	
	Longitude	-98.50795						
SUE	Level of Investigation Req'd		NONE					
	Test Hole No		N/A					
<u> </u>	Test Hole Depth		N/A					
RESOLUTION	Recommended Action		NO CONFLICT					
	Estimated Resolution Date							
	Resolution Status		NO RESOLUTION WAS REQUIRED					
	Comment		Front pole to be Front pole to be Pole diameter	o front pole = 2'-6"				
	Date Collected	8/3/2018 9:5	51:06 AM	<b>Date Modified</b> 12/18/2018 4:01:24 PM			018 4:01:24 PM	

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800