

Utility Conflict Report

R	Utility	SAWS		Corridor	SW MILITA	RY	SITE PHOTOS		
OWNER			F				i i i i i i i i i i i i i i i i i i i		
O	Contact	ANN PECH	E	ID	7049		O OSE OF		
GENERAL INFO	Utility		SANITARY SEWER						
	Size and Material		STANDARD MANHOLE, CAST IRON						
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE			ITE			
	Longitudinal or Crossing		CROSSING						
	Placement Relative to ROW		INSIDE ROW						
LOCATION	Sheet No. 2	208							
	Station 9	926+76.06							
	Offset -	18.31							
	Latitude -	+29.356889							
	Longitude	-98.50810							
SUE	Level of Investigation Req'd		NONE						
	Test Hole No		N/A						
	Test Hole Depth		N/A						
RESOLUTION	Recommended Action		MINIMIZE - PROTECT IN PLACE						
	Estimated Resolution Date								
	Resolution Status		UTILITY OWNER INFORMED OF UTILITY			LITY			
	Comment		Unable to open manhole Edge of pavement to manhole = 3'-8" Manhole to gate track = 4'-0"						
	Date Collected 8/3/2018 9:55:30 AM Date Modified 11/28/2018 6:59:12 AM								

TBPE Firm Registration #470 | TBPLS Firm Registration #10028800