

Utility Conflict Report

| JER | Utility | CPS | | Corridor | SW MILITARY | SITE PHOTOS | |
|--------------|----------------------------------|------------|----------------------------------|----------|--------------|-----------------|--|
| OWNER | Contact | JAKE MAR | TINEZ | ID | 7051 | | |
| GENERAL INFO | Utility | | ELECTRIC | | | | |
| | Size and Material | | STANDARD POWER POLE, TIMBER | | | | |
| | Accessible Route | | ASSET IS INSIDE ACCESSIBLE ROUTE | | | | |
| | Longitudinal or Crossing | | CROSSING | | | | |
| | Placement Relative to ROW | | INSIDE ROW | | | COOK | |
| LOCATION | Sheet No. | 207 | | | | | |
| | Station | 916+26.49 | | | | | |
| | Offset - | set -17.11 | | | | 424684 | |
| | Latitude +29.356819 | | | | State Farm 5 | | |
| | Longitude -98.51141 | | | | | del Degolisch | |
| SUE | Level of Investigation Req'd | | NONE | | | 42 | |
| | Test Hole No | | N/A | | | 424 68 94 | |
| | Test Hole Depth | | N/A | | | | |
| RESOLUTION | Recommended Action | | NO CONFLICT | | | | |
| | Estimated Resolution Date | | | | | *** | |
| | Resolution Status | | NO RESOLUTION WAS REQUIRED | | | | |
| | Comment | | Back of curb to Pole diameter | • | 3" | | |

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800

12/18/2018 4:01:25 PM

Date Modified

Date Collected

8/3/2018 10:23:59 AM