

Utility Conflict Report

| | | | | | | _ | | |
|--------------|---|-------------|----------------------------------|--|-----------|-----|-------------------------|--|
| OWNER | Utility | itility CPS | | Corridor | SW MILITA | ARY | SITE PHOTOS | |
| | Contact | JAKE MAR | TINEZ | ID | 7059 | | | |
| 0 | | | | | | | | |
| GENERAL INFO | Utility | | ELECTRIC | | | | | |
| | Size and Material | | STANDARD POWER POLE, TIMBER | | | | | |
| | Accessible Route | | ASSET IS INSIDE ACCESSIBLE ROUTE | | | TE | | |
| | Longitudinal or Crossing | | CROSSING | | | | | |
| | Placement Relative to ROW | | INSIDE ROW | | | | | |
| LOCATION | Sheet No. 2 | 204 | | | | | | |
| | Station 9 | 10+70.06 | | | | | | |
| | Offset - | 16.84 | | | | | | |
| | Latitude + | -29.356828 | | | | | | |
| | Longitude | -98.51312 | | | | | 50 | |
| SUE | Level of Investigation Req'd | | NONE | | | | EBER OFTC CATY CARLE | |
| | Test Hole No | | N/A | | | | | |
| | Test Hole Depth | | N/A | | | | | |
| RESOLUTION | Recommended Action | | NO CONFLICT | | | | | |
| | Estimated Resolution Date | | | | | | | |
| | Resolution Status | | NO RESOLUTION WAS REQUIRED | | | | | |
| | Comment | | | iameter = 10" of pavement to pole = 3'-0" of asphalt joint = 3'-7" | | | | |
| | Date Collected 8/3/2018 11:05:20 AM Date Modified 12/18/2 | | | | | | 018 4:01:28 PM | |

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800