

## **Utility Conflict Report**

- 4						Ī		
IER.	Utility	CPS		Corridor	SW MILITA	\RY	SITE PHOTOS	
OWNER	Contact	JAKE MAR	ΓINEZ	ID	7063			
							A SOLUTION OF THE PARTY OF THE	
GENERAL INFO	Utility		ELECTRIC					
	Size and Material		STANDARD POWER POLE, TIMBER					
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE					
	Longitudinal or Crossing		CROSSING					
	Placement Relative to ROW		INSIDE ROW					
LOCATION	Sheet No. 2	203						
	Station 9	07+71.08					<b>\</b>	
	<b>Offset</b> -17.42							
	<b>Latitude</b> +29.356786							
	Longitude -	-98.51405					NOBL LO	
SUE	Level of Investigation Req'd		NONE			1221		
	Test Hole No		N/A					
	Test Hole Depth		N/A				150	
RESOLUTION	Recommended Action		NO CONFLICT					
	Estimated Resolution Date						PM ENSINEARS	
	Resolution Status		NO RESOLUTION WAS REQUIRED					
	Comment		Pole ID: 501991 Back of curb to pole = 3'-1" Pole diameter = 10" Pole to back of sidewalk = 2'-0" Relocate pole to ROW with electric lines cantilevered toward the roadway			es		
	Date Collected 8/3/2018 11:17:59 AM Date Modified 12/18/2018 4:01:49 PM							

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800