

## **Utility Conflict Report**

						_		
VER.	Utility	CPS		Corridor	SW MILITAI	RY	SITE PHOTOS	
OWNER	Contact	JAKE MAR	TINEZ <b>ID</b>		7066			
GENERAL INFO	Utility		ELECTRIC					
	Size and Material		STANDARD POWER POLE, TIMBER					
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE					
	Longitudinal or Crossing		CROSSING					
	Placement Relative to ROW		INSIDE ROW					
LOCATION	Sheet No.	203						
	Station	904+74.28						
	Offset	-16.34						
	Latitude	+29.356851					ST PRID WING SP	
	Longitude	-98.51502					Flower Commerce Interest Comme	
SUE	Level of Investigation Req'd		NONE				Urr. Brossman	
	Test Hole No		N/A				RED WING	
	Test Hole Depth		N/A				210	
RESOLUTION	Recommended Action		NO CONFLICT					
	Estimated Resolution Date							
	Resolution Status		NO RESOLUTION WAS REQUIRED					
	Comment		Pole to back of Pole diameter CATV cable Relocate pole	ck of curb to pole = 2'-5" e to back of sidewalk = 2'-6" e diameter = 10"			44 42 46 88 33	
	Date Collected         8/3/2018 11:29:07 AM         Date Modified         12/18/2018 4:01:51 PM							

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800