

## **Utility Conflict Report**

<b>JER</b>	Utility	CPS		Corridor	SW MILITARY	SITE PHOTOS	
OWNER	Contact	JAKE MAR	TINEZ	ID	7067		
GENERAL INFO	Utility		ELECTRIC				
	Size and Material		STANDARD POWER POLE, TIMBER				
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE				
	Longitudinal or Crossing		CROSSING				
	Placement Relative to ROW		INSIDE ROW				
LOCATION	Sheet No.	202					
	Station	903+34.80				8 4 1	
	Offset -16.69 Latitude +29.356806						
						4	
	<b>Longitude</b> -98.51552					6000	
SUE	Level of Investigation Req'd		NONE				
	Test Hole No		N/A N/A			***************************************	
	Test Hole Depth						
RESOLUTION	Recommended Action		NO CONFLICT				
	<b>Estimated Resolution Date</b>						
	Resolution Status		NO RESOLUTION WAS REQUIRED		REQUIRED		
	Comment		Back of curb to Pole to back o Pole diameter	of sidewalk =		20	

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800

12/18/2018 4:01:53 PM

**Date Modified** 

**Date Collected** 

8/3/2018 11:31:35 AM