

Utility Conflict Report

OWNER	Utility	SAWS		Corridor	SW MILITAR	Υ	SITE PHOTOS	
×	Contact	ANN PECH	E	ID	7068			
0								
GENERAL INFO	Utility		SANITARY SEWER					
	Size and Material		STANDARD MANHOLE, CAST IRON					
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE			E		
	Longitudinal or Crossing		CROSSING				1/1	
	Placement Relative to ROW		INSIDE ROW					
LOCATION	Sheet No. 2	202						
	Station 9	903+25.91						
	Offset -18.55							
	Latitude +	-29.356807						
	Longitude	-98.51543						
SUE	Level of Investigation Req'd		NONE					
	Test Hole No		N/A					
	Test Hole Depth		N/A					
RESOLUTION	Recommended Action		MINIMIZE - PROTECT IN PLACE					
	Estimated Resolution Date							
	Resolution Status		UTILITY OWNER INFORMED OF UTILITY			ITY		
	Comment		Unable to open manhole Manhole to concrete driveway joint = 1'-9"					
			Manhole to co Edge of paver		, ,	9"		
			,					
	Date Collected 8/3/2018 11:35:29 AM Date Modified 11/28/2018 6:59:12 AM							

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800