

Utility Conflict Report

0.4							
OWNER	Utility	CPS		Corridor	SW MILITA	RY	SITE PHOTOS
N N	Contact	JAKE MAR	TINEZ	ID	7091		
GENERAL INFO	Utility		ELECTRIC				A STATE OF THE STA
	Size and Material		STANDARD POWER POLE, TIMBER				The state of the state of
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUT			ITE	
	Longitudinal or Crossing		CROSSING				
	Placement Relative to ROW		INSIDE ROW				
LOCATION	Sheet No.	197					
	Station 8	364+01.74					
	Offset -	14.91					
	Latitude -	29.356694					RES
	Longitude	-98.52777					ST WI
SUE	Level of Investigation Req'd		NONE				
	Test Hole No		N/A				
	Test Hole Depth		N/A				
RESOLUTION	Recommended Action		NO CONFLICT				
	Estimated Resolution Date						T 00
	Resolution Status		NO RESOLUTION WAS REQUIRED				McDonald
	Comment		Back of curb t Pole to back of Pole diameter No pole ID	of sidewalk =			
	Date Collected	8/3/2018 3:0	2:22 PM Date Modified 12/18			12/18/2	018 4:01:56 PM

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800