

Utility Conflict Report

ER	Utility	SAWS		Corridor	SW MILITAF	RY	SITE PHOTOS		
OWNER	Contact	ANN PECH		7092					
GENERAL INFO	Utility		WATER						
	Size and Material		STANDARD WATER VALVE, CAST IRON						
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE						
	Longitudinal or Crossing		CROSSING						
	Placement Relative to ROW		INSIDE ROW						
LOCATION	Sheet No. 1	97							
	Station 8	863+88.87							
	Offset -	17.43							
	Latitude +	29.356837							
	Longitude -	-98.52786							
SUE	Level of Investigation Req'd		NONE						
	Test Hole No		N/A						
	Test Hole Depth		N/A						
RESOLUTION	Recommended Action		MINIMIZE - PROTECT IN PLACE				McPopale		
	Estimated Resolution Date		UTILITY OWNER INFORMED OF UTILITY Valve to back of sidewalk = 2'-4" Top of valve to surface = 3'-8" Lid thickness = 2"			The second secon			
	Resolution Status					₋ITY			
	Comment								
	Date Collected 8/3/2018 3:05:29 PM Date Modified 11/28/2018 6:59:12 AM								

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800