

Utility Conflict Report

| ER | Utility | CPS | | Corridor | SW MILITAF | ιRY | SITE PHOTOS |
|--|----------------------------------|------------|-----------------------------------|--|------------|-----|--|
| OWNER | Contact | JAKE MAR | TINEZ | ID | 7098 | | |
| GENERAL INFO | Utility | | ELECTRIC | | | | X |
| | Size and Material | | STANDARD POWER POLE, TIMBER | | | | |
| | Accessible Route | | ASSET IS OUTSIDE ACCESSIBLE ROUTE | | | UTE | |
| | Longitudinal or Crossing | | CROSSING | | | | |
| | Placement Relative to ROW | | INSIDE ROW | | | | |
| LOCATION | Sheet No. 1 | 95 | | | | | |
| | Station 8 | 356+84.08 | | | | | |
| | Offset - | 16.4772 | | | | | |
| | Latitude + | -29.356782 | | | | | |
| | Longitude | -98.52995 | | | | | |
| SUE | Level of Investigation Req'd | | NONE | | | | The same of the sa |
| | Test Hole No | | N/A | | | | |
| | Test Hole Depth | | N/A | | | | |
| RESOLUTION | Recommended Action | | NO CONFLICT | | | | |
| | Estimated Resolution Date | | | | | | MEG |
| | Resolution Status | | NO RESOLUTION WAS REQUIRED | | | | |
| | Comment | | | o pole = 2'-11" nlet to pole = 2'-0" = 10" | | | |
| Date Collected 8/3/2018 3:35:08 PM Date Modified 11/28/2018 6:59:12 AM | | | | | | | |

TBPE Firm Registration #470 I TBPLS Firm Registration #10028800