

## **Utility Conflict Report**

OWNER	Utility	CPS		Corridor ID	SW MILITA	ARY	SITE PHOTOS
	Contact	JAKE MAR	TINEZ				
0							
	Utility		ELECTRIC				
GENERAL INFO	Size and Material		STANDARD POWER POLE, TIMBER				
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROU		JTE		
	Longitudinal or Crossing		CROSSING				
۵	Placement Relative to ROW		INSIDE ROW				
LOCATION	Sheet No. 1	98					
	Station 8	344+78.09					
	Offset -	16.32					
	Latitude +	-29.356819					
	Longitude -	-98.53384					5 dp.
SUE	Level of Investigation Req'd		NONE				
	Test Hole No		N/A				4
0,	Test Hole Depth		N/A				
RESOLUTION	Recommended Action		NO CONFLIC	Т			
	Estimated Resolution Date						and the second
	Resolution Status		NO RESOLUTION WAS REQUIRED				
	Comment		Pole marking: Pole to back of Back of curb to Guy wire at ba Pole diameter	le ID: 480094; LW39974 le marking: 240; 2435 le to back of sidewalk = 2'-10" ck of curb to pole = 2'-9" ly wire at back of sidewalk le diameter = 12" jacent to existing VIA bus stop			
	Date Collected	3:25 AM	Date I	Modified	12/18/2	2018 4:02:02 PM	