

## **Utility Conflict Report**

ER	Utility	SAWS		Corridor ID	SW MILITARY	RY.	SITE PHOTOS		
OWNER	Contact	ANN PECH	E						
0							the great way and		
GENERAL INFO	Utility		WATER			the state of the s			
	Size and Material		STANDARD WATER VALVE, CAST IRON						
	Accessible Route		ASSET IS OUTSIDE ACCESSIBLE ROUTE						
	Longitudinal or Crossing		CROSSING			300			
	Placement Relative to ROW		INSIDE ROW						
LOCATION	Sheet No.	186							
	Station 7	785+47.93							
	Offset -	13.8765							
	Latitude -	29.357754							
	Longitude	-98.55237							
SUE	Level of Investigation Req'd		NONE						
	Test Hole No		N/A						
	Test Hole Depth		N/A			1000			
RESOLUTION	Recommended Action		MINIMIZE - PROTECT IN PLACE						
	Estimated Resolution Date					STO			
	Resolution Status		UTILITY OWNER INFORMED OF UTILITY						
	Comment		Unable to open lid						
			Back of curb to valve = 9"						
Date Collected 8/6/2018 9:58:19 AM Date Modified 12/18/2018 7:20 AM									

TBPE Firm Registration #470 | TBPLS Firm Registration #10028800