

Utility Conflict Report

ER	Utility	SAWS		Corridor	SW MILITA	RY	SITE PHOTOS		
OWNER	Contact	ANN PECH	F	ID	7143				
Ó	Contact	7 2011	_		7 140				
GENERAL INFO	Utility		SANITARY SEWER						
	Size and Material		STANDARD MANHOLE, CAST IRON						
	Accessible Route		ASSET IS INSIDE ACCESSIBLE ROUTE						
	Longitudinal or Crossing		CROSSING						
	Placement Relative to ROW		INSIDE ROW						
LOCATION	Sheet No.	174					25		
	Station 7	759+35.58							
	Offset -	17.5802							
	Latitude -	-29.358516							
	Longitude	gitude -98.56058							
SUE	Level of Investigation Req'd		NONE						
	Test Hole No		N/A						
	Test Hole Depth		N/A						
RESOLUTION	Recommended Action		MINIMIZE - PROTECT IN PLACE				The same of the sa		
	Estimated Resolution Date								
	Resolution Status		UTILITY OWNER INFORMED OF UTILITY			ILITY			
	Comment		Back of curb to manhole = 3'-2" Unable to open manhole Manhole adjacent to edge of driveway						
Date Collected 8/6/2018 1:11 PM Date Modified 12/17/2018 4:56:36 PM									