

Utility Conflict Report

OWNER	Utility	AT&T	Corridor	BANDERA	SITE PHOTOS
	Contact	PHILIP AUSTIN	ID	4573	
GENERAL INFO	Utility	COMMUNICATIONS			
	Size and Material	UNKNOWN			
	Accessible Route	ASSET IS OUTSIDE ACCESSIBLE ROUTE			
	Longitudinal or Crossing	LONGITUDINAL			
	Placement Relative to ROW	INSIDE ROW			
LOCATION	Sheet No.	231			
	Station	1354+00			
	Offset	35			
	Latitude	+29.491326			
	Longitude	-98.61282			
SUE	Level of Investigation Req'd	QLA			
	Test Hole No	N/A			
	Test Hole Depth	N/A			
RESOLUTION	Recommended Action	ACCOMODATE - RELOCATION			
	Estimated Resolution Date				
	Resolution Status	UTILITY CONFLICT CREATED			
	Comment	811- underground communication cables/conduit running beneath Seneca Dr where RCP is proposed.			
Date Collected		11/20/2018 9:29:15 AM		Date Modified 11/21/2018 2:51:37 PM	

